

**EE321 Exam 3  
Spring 2010**

**Notes: You must show work for credit.**

**Trigonometric identities are towards the back.**

**The last page of exam is blank for extra paper if needed.**

- 1) 18 pts. Consider the a-phase of a distributed winding machine. The number of conductors in each slot is given by

$$N_{as} = [0 \ 4 \ 4 \ 0 \ -4 \ -4 \ 0 \ 4 \ 4 \ 0 \ -4 \ -4]$$

The total flux through each of the teeth is given by

$$\Phi = [-1 \ -2 \ -1 \ 1 \ 2 \ 1 \ -1 \ -2 \ -1 \ 1 \ 2 \ 1]$$

where the first element is the flux through the first tooth and so forth. What is the winding function (12 pts)? What is the flux linking the a-phase winding (i.e. what is  $\lambda_{as}$ ) (6 pts)?

In  $N_{as}$  044 0-4-4 pattern repeats twice

$$\Rightarrow \frac{P}{2} = 2 \Rightarrow P = 4$$

$$W_{as,1} = \frac{1}{2} (0 + 4 + 4) = 4$$

$$W_{as,2} = W_{as,1} - N_{as,1} = 4 \text{ so on.}$$

$$\Rightarrow W_{as} = [4 \ 4 \ 0 \ -4 \ -4 \ 0 \ 4 \ 4 \ 0 \ -4 \ -4 \ 0]$$

$$\lambda_{as} = W_{as}^T \Phi$$

$$= -4 - 8 + 0 - 4 - 8 + 0 - 4 - 8 + 0 - 4 - 8 + 0$$

$$\lambda_{as} = -48 \text{ Vs}$$

- 2) 18 pts. The a- and b-phase winding functions of a two-phase machine may be expressed

$$w_{as} = 50 \sin(4\phi_{sm})$$

$$w_{bs} = 50 \cos(4\phi_{sm})$$

where  $\phi_{sm}$  is measured in the counterclockwise direction (as is our custom). The a- and b-phase currents may be expressed

$$i_{as} = 100 \sin(50t)$$

$$i_{bs} = -100 \cos(50t)$$

The machine has a uniform airgap of  $\pi$  mm, a stator radius of 2 cm, and a length of  $50/\pi$  cm, and there are no circuits on the rotor, PM materials, or other complications.

- Part A. Find an expression for the radial component of the  $B$ -field in terms of  $\phi_{sm}$  and  $t$ . (9pts)  
 Part B. What is the speed of the  $B$  field traveling wave in the counterclockwise direction? (3 pts)  
 Part C. Neglecting the resistance of the a-phase winding, what is the voltage across the a-phase in terms of time. (6 pts)

Part A  $F = w_{as} i_{as} + w_{bs} i_{bs}$

$$= 5000 (\sin 4\phi_{sm} \sin 50t - \cos 4\phi_{sm} \cos 50t)$$

Using Trig ID  $\cos(A \pm B) = \cos A \cos B \mp \sin A \sin B$

$$F = -5000 \cos(4\phi_{sm} + 50t) \text{ or } 5000 \cos(4\phi_{sm} + 50t + \pi)$$

PART B

$$B = \mu_0 H = \mu_0 \frac{F}{g} = \frac{4\pi \times 10^{-7} \times 5000}{\pi \times 10^{-3}} \cos(4\phi_{sm} + 50t + \pi)$$

$$= 2 \cos(4\phi_{sm} + 50t + \pi) \text{ T}$$

differentiate  $4\phi_{sm} + 50t + \pi = k$  w.r.t. time

$$\Rightarrow \frac{d\phi_{sm}}{dt} = -\frac{50}{4} = -12.5 \text{ rad/s}$$

in counter clockwise direction

(extra paper for problem 2)

Part c

$$\lambda_{as} = \pi L \int_0^{2\pi} B W_{as} d\phi_{sm}$$

$$= 2 \times 10^{-2} \times \frac{50}{\pi} \times 10^{-2} \times 2 \times 5000 \int_0^{2\pi} \cos(50t + 4\phi_{sm} + \pi) \sin 4\phi_{sm} d\phi_{sm}$$

Using Trig ID  $\sin A \cos B = \frac{1}{2} (\sin(A+B) + \sin(A-B))$

$$= \frac{1}{\pi} \cdot \frac{1}{2} \int_0^{2\pi} \sin(50t + 4\phi_{sm} + \pi) + \sin(-50t - \pi) d\phi_{sm}$$

$$= \frac{-1}{2\pi} \int_0^{2\pi} \sin(50t + \pi) d\phi_{sm} = \frac{-\sin(50t + \pi)}{2\pi} \Big]_0^{2\pi}$$

$$= -\sin(50t + \pi) V_s$$

$$V_{as} = \frac{d\lambda_{as}}{dt} = -50 \cos(50t + \pi) V$$

$$V_{as} = 50 \cos 50t V$$

- 3.) 18 pts. A two-phase permanent magnet synchronous machine has the following flux linkage equation. Take it to be correct even though it doesn't make complete sense.

$$\begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \end{bmatrix} = \begin{bmatrix} 5 & -2 \\ -2 & 5 \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \end{bmatrix} + \begin{bmatrix} 5 \\ 3 \end{bmatrix}$$

Now consider the following two-phase qd transformation to the 'weird' reference frame

$$\begin{bmatrix} f_{qs}^w \\ f_{ds}^w \end{bmatrix} = \mathbf{K}_s^w \begin{bmatrix} f_{as} \\ f_{bs} \end{bmatrix}$$

$$\mathbf{K}_s^w = \begin{bmatrix} 5 & 2 \\ 2 & 1 \end{bmatrix} \Rightarrow \mathbf{K}_s^{w^{-1}} = \frac{1}{1} \begin{bmatrix} 1 & -2 \\ -2 & 5 \end{bmatrix}$$

Express the machine flux linkage equations in the weird reference frame.

$$\lambda_{qds}^w = \mathbf{K}_s^w \bar{\mathbf{L}} \mathbf{K}_s^{w^{-1}} i_{qds}^w + \mathbf{K}_s^w \begin{bmatrix} 5 \\ 3 \end{bmatrix}$$

$$= \begin{bmatrix} 5 & 2 \\ 2 & 1 \end{bmatrix} \begin{bmatrix} 5 & -2 \\ -2 & 5 \end{bmatrix} \begin{bmatrix} 1 & -2 \\ -2 & 5 \end{bmatrix} i_{qds}^w + \begin{bmatrix} 5 & 2 \\ 2 & 1 \end{bmatrix} \begin{bmatrix} 5 \\ 3 \end{bmatrix}$$

$$= \begin{bmatrix} 5 & 2 \\ 2 & 1 \end{bmatrix} \begin{bmatrix} 9 & -20 \\ -12 & 29 \end{bmatrix} i_{qds}^w + \begin{bmatrix} 31 \\ 13 \end{bmatrix}$$

$$\lambda_{qds}^w = \begin{bmatrix} 21 & -42 \\ 6 & -11 \end{bmatrix} i_{qds}^w + \begin{bmatrix} 31 \\ 13 \end{bmatrix}$$

- 4.) 18 pts. A three phase brushless DC machine has the following parameters:  $r_s = 3\Omega$ ,  $L_{ss} = 10$  mH,  $\lambda_m = 0.17$  Vs,  $P = 4$ . At is desired to operate at obtain a torque of 2 Nm at a speed of 4000 RPM. What is the highest machine efficiency that can be obtained to achieve the desired torque at the desired speed.

for optimum efficiency set  $i_{ds}^r = 0$

$$\text{from } T_e = \frac{3}{2} \frac{P}{2} \lambda_m i_{qs}^r$$

$$i_{qs}^r = \frac{2}{\frac{3}{2} \times \frac{4}{2} \times 0.17} = 3.921 \text{ A}$$

$$\omega_{rm} = 4000 \times \frac{2\pi}{60} = \frac{400\pi}{3} \text{ rad/s}$$

$$\omega_r = \frac{P}{2} \omega_{rm} = \frac{4}{2} \frac{400\pi}{3} = \frac{800\pi}{3}$$

$$V_{qs}^r = r_s i_{qs}^r + \cancel{\omega_r L_{ss} i_{ds}^r} + \omega_r \lambda_m$$

$$= 154.18 \text{ V}$$

$$P_{in} = \frac{3}{2} (V_{qs}^r i_{qs}^r + \cancel{V_{ds}^r i_{ds}^r})$$

$$= 1.5 (154.18 \times 3.92) = 906.82$$

$$P_{out} = T_e \omega_{rm}$$

$$= 2 \times \frac{400\pi}{3} = \frac{800\pi}{3} = 837.76 \text{ W}$$

$$\eta = \frac{P_{out}}{P_{in}} = \frac{837.76}{906.82} = 0.9238 \text{ or } 92.38\%$$

5.) 28 pts. Answer true or false. Grading on each is as follows: Correct(2pts), Incorrect(-1pt), No response (0 pts).

ANSWER (T-True, F-False)

T a.) Distributed windings are used to create a smoothly rotating MMF waves.

T b.) Continuous and discrete winding descriptions are both used to represent distributed windings.

F c.) In a distributed winding machine, the conductor density function serves a similar role to turns in our lumped winding analysis.

T d.) In many ac machines, the rotor moves at the same speed as the MMF wave.

T e.) The speed of the stator MMF wave is controlled by the frequency of the currents and the number of poles.

T f.) In a distributed winding machines with a uniform airgap and a round iron rotor (as we discussed in class), the radial flux density is a sinusoidal function in space (i.e.  $\phi_{sm}$ )

T g.) In a distributed winding machine with a uniform airgap and a round iron rotor (as we discussed in class), the radial flux density is a sinusoidal function of time.

T h.) In practice, "single-phase" machines are actually two-phase machines.

T i.) All other factors being as equal as possible, a three-phase machine fed from a three-phase bus will be more efficient than a single-phase machine.

TOY F j.) Flux is your friend.

F k.) Obtaining a sinusoidal back emf in a brushless dc machine requires a specific magnet shape.

F l.) Setting  $\phi_v = \text{atan}(\omega_r L_{ss} / r_s)$  yields maximum efficiency.

F m.) Voltage controlled brushless dc motor drives are, in general, more efficient than current-sourced drives.

T n.) Permanent magnets contribute to co-energy.